

Instrucciones de montaje · Assembly Instructions

CO-1836 SWING

ES • IMPORTANTE: A CONSERVAR PARA FUTURAS CONSULTAS. LÉASE ATENTAMENTE.

EN • IMPORTANT: PLEASE KEEP FOR FUTURE REFERENCE. READ CAREFULLY.

FR • ATTENTION: CONSERVER POUR CONSULTER AU FUTUR.


IT • IMPORTANTE: LEGGERE ATTENTAMENTE LE ISTRUZIONE. TENERE PER FUTURE CONSULTAZIONE.

PT • IMPORTANTE: MANTENHA PARA FUTURAS CONSULTAS. LÉASE ATENTAMENTE.

R • ВАЖНО: СОХРАНИТЕ ДЛЯ ДАЛЬНЕЙШЕГО ИСПОЛЬЗОВАНИЯ. ВНИМАТЕЛЬНО ПРОЧИТАЙТЕ.

A • هام. احفظ للمراجعة. اقرأ جيداً قبل الاستعمال

CN • 重要事项：保留以备将来参考，请仔细阅读。





60'




NOT INCLUDED



ALLEN 4MM




C01235
X18




C04790
X12



C01537
X20



C01538
X20










C00329
X1




C01419
X8












C07969
M6x25
X18







x3












3



4










7



C07969
M6x25
X6



8



9



C10604
X 1



C09061
X 2



C01235
X 9

10





C10605
X 1








C09061
X 2






C01235
X 9





11





12




OK





13





OK



C00329
X1



C04790
X6



OK